State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

HO1 03	ED	BRADENHEAD T	EST REPO	RT			
Property Name BRADENHEAD TEST REPORT Operator Name CHEVRON USA \\ Property Name					30-025-02749		
Property Name					Well No.		
VACUUM GRAYBURG SAN ANDRES UNIT						4	4
		7. Surface Loc	ation				
UL - Lot Section T	Township Range 185 34E	Feet from N/S Line 1980 N			Feet From E		County
		Well Stat	us				
Well Status	SHUT-IN		PRODUCING		DATE		
				3-14	3-14-17		
OPEN I	BRADENHEAD AND IN	TERMEDIATE TO ATMOSP	HERE INDIVIDU	ALLY FOR 15	MINUTES	SEACH	
If bradenhead flowed water,	check all of the descriptio	OBSERVED I	DATA				
A Dividendend Howell Whitely	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-P	rod	(D)Prod Csng		(E)Tubing
Pressure	0	0					11/2
Flow Characteristics	-		<u> </u>			20	140
Puff	⊘ / N	Y/60	Y	/ N	1	Y/N	
Steady Flow	Y/Ø	Y/10	Y	/ N	Y	7 / N	1
Surges	YID	YID	Y	/ N	Y	7 / N	1
Down to nothing	Ø/N	Ø/ N		/ N		7 / N]
Gas or Oil	Y / 🐼	Y/Ø		/ N		Y/N	
Water	Y / 🔕	Y/B	Y	/ N	Y	7 / N	
If bradenhead flowed water,	check all of the descriptio	ns that apply:					
CLEAR			LFUR	UR BLACK			
Remarks:		,	INJECTING A	T THIS TIME	WT	R,GAS	s,CO2
	u.						
Signature:	0 /						
Link Khron				OIL CONSERVATION DIVISION			
Printed name: Linda Robinson				Entered into RBDMS			
Title: Field Specialist A				Re-test			
E-mail Address: LRUW@CHEVRON.COM						V	
Date: 3-14-17 Phone: 575-704-2225					\triangle		
mailed 3	Witness:				7		
U U	•			On the same interest and the			