

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron midcontinent L.P. API Number 30-025-03898  
Property Name WLU west Livingston Unit Well No. 58

7. Surface Location

|           |           |            |            |             |          |             |          |            |
|-----------|-----------|------------|------------|-------------|----------|-------------|----------|------------|
| UI. - Lot | Section   | Township   | Range      | Feet from   | N/S Line | Feet From   | E/W Line | County     |
| <u>5</u>  | <u>07</u> | <u>17S</u> | <u>36E</u> | <u>1980</u> | <u>S</u> | <u>1980</u> | <u>E</u> | <u>Lea</u> |

Well Status

|             |         |            |                |
|-------------|---------|------------|----------------|
| Well Status | SHUT-IN | PRODUCING  | DATE           |
|             |         | <u>Inj</u> | <u>3-16-17</u> |

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Csgng | (E)Tubing   |
|----------------------|----------------|------------------------|----------------|---------------|-------------|
| Pressure             | <u>0</u>       | <u>0</u>               | <u>N/A.</u>    | <u>00</u>     | <u>1400</u> |
| Flow Characteristics |                |                        |                |               |             |
| Puff                 | <u>Y/N</u>     | <u>Y/N</u>             | <u>Y/N</u>     | <u>Y/N</u>    | <u>Y/N</u>  |
| Steady Flow          | <u>Y/N</u>     | <u>Y/N</u>             | <u>Y/N</u>     | <u>Y/N</u>    | <u>Y/N</u>  |
| Surges               | <u>Y/N</u>     | <u>Y/N</u>             | <u>Y/N</u>     | <u>Y/N</u>    | <u>Y/N</u>  |
| Down to nothing      | <u>Y/N</u>     | <u>Y/N</u>             | <u>Y/N</u>     | <u>Y/N</u>    | <u>Y/N</u>  |
| Gas or Oil           | <u>Y/N</u>     | <u>Y/N</u>             | <u>Y/N</u>     | <u>Y/N</u>    | <u>Y/N</u>  |
| Water                | <u>Y/N</u>     | <u>Y/N</u>             | <u>Y/N</u>     | <u>Y/N</u>    | <u>Y/N</u>  |

If bradenhead flowed water, check all of the descriptions that apply:

|              |              |              |               |              |
|--------------|--------------|--------------|---------------|--------------|
| <u>CLEAR</u> | <u>FRESH</u> | <u>SALTY</u> | <u>SULFUR</u> | <u>BLACK</u> |
|--------------|--------------|--------------|---------------|--------------|

Remarks:

INJECTING AT THIS TIME WTR, GAS, CO2

|                                         |                           |
|-----------------------------------------|---------------------------|
| Signature: <u>[Signature]</u>           | OIL CONSERVATION DIVISION |
| Printed name: <u>Eloy Carranza</u>      | Entered into RBLMS        |
| Title: <u>Pumper</u>                    | Re-test <u>727</u>        |
| E-mail Address: <u>EB75@Chevron.com</u> |                           |
| Date: <u>3-16-17</u>                    |                           |
| Phone: <u>970-747 6151</u>              |                           |
| mailed <u>3:30</u>                      |                           |
| Witness:                                |                           |