

APR 06 2017

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	Chewon midcontinent L.P.	API Number	30-025-08099
Property Name	LPU Louisa Paddock Unit	Well No.	601

Surface Location

U/L - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
E	01	17S	30E	1980	N	990	W	Lea

Well Status

Well Status	SHUT-IN	PRODUCING	DATE	
			3-10-17	Inj

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULEUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

TAID

Signature: Jesse Covarrubia	OIL CONSERVATION DIVISION
Printed name: Jesse Covarrubia	Entered into RBDMS
Title: FS	Re-test
E-mail Address: Lfuo@chevron.com	
Date: 3-10-17	
Phone: 575-704-2180	
mailed 4:3	
Witness:	