

HOBBS OCD  
APR 17 2017  
RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

|                                            |                             |
|--------------------------------------------|-----------------------------|
| Operator Name<br>Chevron USA Inc           | API Number<br>30-025-3226 2 |
| Property Name<br>Vacuum Gibrleta West Unit | Well No.<br>15              |

7. Surface Location

|               |               |                 |              |                  |               |                  |               |               |
|---------------|---------------|-----------------|--------------|------------------|---------------|------------------|---------------|---------------|
| UL - Lot<br>A | Section<br>25 | Township<br>17S | Range<br>34E | Feet from<br>807 | N/S Line<br>N | Feet From<br>971 | E/W Line<br>E | County<br>Lea |
|---------------|---------------|-----------------|--------------|------------------|---------------|------------------|---------------|---------------|

Well Status

|             |         |                  |                 |
|-------------|---------|------------------|-----------------|
| Well Status | SHUT-IN | PRODUCING<br>Yes | DATE<br>3-22-17 |
|-------------|---------|------------------|-----------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm   | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Csg | (E)Tubing |
|----------------------|------------------|------------------------|----------------|-------------|-----------|
| Pressure             | 0                | —                      | —              | 29          | 250       |
| Flow Characteristics |                  |                        |                |             |           |
| Puff                 | Y / <del>N</del> | Y / N                  | Y / N          | Y / N       |           |
| Steady Flow          | Y / <del>N</del> | Y / N                  | Y / N          | Y / N       |           |
| Surges               | Y / <del>N</del> | Y / N                  | Y / N          | Y / N       |           |
| Down to nothing      | <del>Y</del> / N | Y / N                  | Y / N          | Y / N       |           |
| Gas or Oil           | Y / <del>N</del> | Y / N                  | Y / N          | Y / N       |           |
| Water                | Y / <del>N</del> | Y / N                  | Y / N          | Y / N       |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks: INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

|                                  |                           |
|----------------------------------|---------------------------|
| Signature: Sergio Urias          | OIL CONSERVATION DIVISION |
| Printed name: Sergio Urias       | Entered into RBDMS        |
| Title: Field Specialist          | Re-test                   |
| E-mail Address: uesf@chevron.com |                           |
| Date: 3-22-17                    | Phone: 575-704-6899       |
| 4.13.17                          | Witness:                  |