

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office


BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC	API Number 3002531990
Property Name NM R ST OCT-1	Well No. 13

7. Surface Location

UL - Lot G	Section 6	Township 18	Range 35	Feet from 1905	N/S Line FNL	Feet From 2130	E/W Line FEL	County LEA
----------------------	---------------------	-----------------------	--------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN 	PRODUCING 	DATE 3/23/17
-------------	---	---	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0	—	—	0	Vac.
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR 	FRESH 	SALTY 	SULFUR 	BLACK 
---	---	---	--	---

Remarks:

INJECTING AT THIS TIME ☐ WTR, ☐ GAS, ☐ CO2

Waiting on pulling unit - hole in tubing

Signature: 	OIL CONSERVATION DIVISION
Printed name: Alex Ormsby	Entered into RBDMS 
Title: Field Specialist	Re-test
E-mail Address: EBXF@CHEVRON.com	
Date: 3/23/17	
4.13.17	
Phone: (575) 513-5524	
Witness:	