## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

HODBS OCD

APR 1 7 2017

BRADENHEAD TEST REPORT

CHEURON USA INC 30									DASTINGSED		
Property Name									Well No.		
		0	HIE	A							
					7. Surface Loca			Feet From			
		Township	The second secon		Feet from 500		FNL S		FEL E/W Line	County LEA	
	1 ' 1				Well Statu			590			
Well	Status	1	SHUT-IN		PRODUCIN			DATE			
Wen States							3/23,		177		
	OPEN	BRADENH	EAD AND INT	TERMEDI	ATE TO ATMOSPI	HERE INDIV	VIDUALLY	FOR 15 MINUT	ES EACH		
					OBSERVED D	ATA					
If bradenhead	d flowed water		of the description								
n			(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		d Csng	(E)Tubing	
Pressure			Ø		N/A		N/A		2	310	
Flow Charac			6								
Puff		Y	Y / 🔞		Y / N Y / N		Y / N Y / N		Y / N Y / N		
Steady Flow Surges			Y / (X)		Y/N		Y/N		Y/N		
Down to nothing		-	0) / N		Y/N		Y / N		Y/N		
Gas or Oil			Y/®		Y/N		Y / N		Y / N		
Water			Y / 6		Y / N		Y / N		Y / N		
				1							
If bradenhead	d flowed water	, check all	of the description	ons that ap	ply:						
CLEAR		FRES	FRESH		SALTY		SULFUR		BLACK		
Remarks:						INJECT	ING AT TI	HISTIME	WTR,	GAS,CO2	
Signature: Olex amos								OIL CONSERVATION DIVISION			
	Printed name: ACEX ORMSBY							Entered into RBDMS			
Title: Field Specialist								Re-test			
E-mail Address: EBXFQCHEVRON, Com											
Date: 3/23/2017 Phone: (575) 5/3-55 2/									4 )		
4	13.17		Witness:					ii .		and a management and the latter and	
							0	CONDUCTOR OF THE PROPERTY OF T		Committee Bulletin Committee Committ	