District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-620

State of New Mexico

APR 1 7 2017

Energy, Minerals and Natural Resources DepartmentOil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT						
CHEVRON USA				30-025-02113		
CENTRAL VACUUM UNIT				•	Well No. 22	
7. Surface Location						
JL-Lot Section Tow 35	75 Range	Feet from	N/S Line	Feet From	E/W Line	County LEA
Well Status						
Well Status SHUT-IN PRODUCING		IG 3	3-22-17			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:						
	(A)Surf-Interm (B)Interm(1)-Interm(2) (C)Interm-Prod		(D)Prod	Csng	(E)Tubing	
Pressure	0	_	_	1	00	150
Flow Characteristics	2					
Puff	Y/N)	Y / N	Y / N		Y/N	
Steady Flow	Y / (N)	Y/N	Y/N		Y / N	
Surges	0	Y/N	Y/N		Y / N	
Down to nothing Gas or Oil	Y/N	Y / N Y / N	Y/N Y/N		Y / N Y / N	
Water	Y/N)	Y/N	Y/N		Y / N	

If bradenhead flowed water, check all of the descriptions that apply:						
CLEAR FRESH SALTY SUI		SULFU	R	BLACK		
Remarks: INJECTING AT THIS TIMEWTR,GAS,CO2						
Signature					SEDVATION	NOISION
10 CM				OIL CONSERVATION DIVISION		
Printed name: RUBEN RODRIGUEZ				Entered into RBDMS		
Title: FSA				Re-test		
E-mail Address: TZCL@CHEVRON.COM						
Date: 3 - 22 - 17 Phone: 575-513-5526					F	
Mailed 4.13.1	Witness:					