District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 FC (373) 193-0720

State of New Mexico

APR 1 7 2017 Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RECEIVED BRADENHEAD TEST REPORT		
CHEVRON USA INC 30-025-08	453	
	/ell No.	
⁷ Surface Location		
UL-Lot Section Township Range Feet from N/S Line Feet From E/W Line T 25 175 34E 1980 5 660 E	County	
I 25 175 34E 1980 5 660 E Well Status	LLII	
Well Status SHUT-IN PRODUCING DATE		
3 - 22 - 17		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:		
(A)Surf-Interm (B)Interm(1)-Interm(2) (C)Interm-Prod (D)Prod Csng	(E)Tubing	
Pressure 0 - 160	380	
Flow Characteristics		
Puff Y/N Y/N Y/N		
Steady Flow Y/N Y/N Y/N		
Surges Y/N Y/N Y/N		
Down to nothing W N Y / N Y / N Y / N		
Gas or Oil Y/N Y/N Y/N		
Water Y/N Y/N Y/N		
If bradenhead flowed water, check all of the descriptions that apply:		
CLEAR FRESH SALTY SULFUR BLACK		
Remarks: INJECTING AT THIS TIME WTR, GAS,CO2		
Signature: OIL CONSERVATION DIVISION		
Printed name: RUBEN RODRIGUEZ Entered into RBDMS		
Title: FSA Re-test		
	T VM	
E-mail Address: TZCL@CHEVRON.COM		
E-mail Address: TZCL@CHEVRON.COM Date: 3-22-17 Phone: 575-513-5526		