

HOBBS OCD

APR 03 2017

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Apache Oil Corp.		API Number 30-025-06388	
Property Name NEDU (North East drinkard unit)		Well No. 301	

¹ Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
4	3	21	37	1980	S	660	W	Lea

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 3/23/17
------------------	-------------------------------------	----------------	-------------------------------------	--	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	Ø	Ø	N/A	46±0	1000
<u>Flow Characteristics</u>					
Puff	Y / ☒ N	Y / ☒ N	Y / N	☒ Y / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ Y / ☒ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	☒ Y / N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Air-gas blow down Less than 1 min.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: tracy.cole@apachecorp.com			
Date: 3/23/17	Phone: 575-441-5196		
Witness:			