

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

APR 03 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		* API Number 30-025-06509	
Property Name NEDU (Northeast drinkard unit)		Well No. 112	

1. Surface Location

UL - Lot A	Section 3	Township 21	Range 37	Feet from 660'	N/S Line N	Feet From 660'	E/W Line E	County Lea
----------------------	---------------------	-----------------------	--------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL ☒ NO	YES	SHUT-IN ☒ NO	☒ INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 3/7/17
-----	--	-----	--	--------------------------------------	----------	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	Ø	Ø	N/A	Ø	1100
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / ☒ N	☒ Y / N	CO2 —
Steady Flow	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	WTR ✓
Surges	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	GAS —
Down to nothing	Y / ☒ N	Y / ☒ N	Y / ☒ N	☒ Y / N	Type of Fluid Inferred for Wellhead & applies.
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: Tracy.Cole@apachecorp.com			
Date:	Phone: 575-441-5196		
Witness:			