

4.12.17

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

BRADENHEAD TEST REPORT

APR 21 2017 RECEIVED	Operator Name	3 rd API Number
	Chevron USA INC	30-025-25793
	Property Name	Well No.
	Central Vacuum Unit	16

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
G	30	175	35E		2630	N	1330	E	Lea

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
		✓	4-4-17

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:



	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0	—	—	0	1571
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Down to nothing	☒ / N	Y / N	Y / N	☒ / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
✓	✓	✓	✓	✓

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZYR@Chevron.com	
Date: 4-4-17	
Phone: 575-390-4449	
Witness:	