

HOBBS OCD

APR 21 2017

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A INC	API Number 30-025-31132
Property Name Vacuum GLORIA WEST UNIT	Well No. 114 #

7. Surface Location

UL - Lot B	Section 1	Township 18S	Range 34E	Feet from 280	N/S Line N	Feet From 2080	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status ✓	SHUT-IN	PRODUCING ✓	DATE 4-6-17
-------------------------	---------	-----------------------	-----------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0	✓	✓	40	350
Flow Characteristics					
Puff	Y / X	Y / N	Y / N	Y / N	
Steady Flow	Y / X	Y / N	Y / N	Y / N	
Surges	Y / X	Y / N	Y / N	Y / N	
Down to nothing	Y / X	Y / N	Y / N	Y / N	
Gas or Oil	Y / X	Y / N	Y / N	Y / N	
Water	Y / X	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: Austin Boone	OIL CONSERVATION DIVISION
Printed name: Austin Boone	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: ctym@chevron.com	
Date: 4-6-17	Phone: 575-513-0363
Witness:	