

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

MAY 01 2017

BRADENHEAD TEST REPORT

Operator Name <i>Legacy</i>	API Number 30-005-29147
Property Name Rock Queen Unit	Well No. 303

7. Surface Location

UL - Lot H	Section 25	Township 13S	Range 31E	Feet from 1880	N/S Line N	Feet From 660	E/W Line E	County Chaves
---------------	---------------	-----------------	--------------	-------------------	---------------	------------------	---------------	------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR NO	PRODUCER OIL	DATE 4-10-2017
------------------	----------------	----------------	-----------------	-------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	—	—	Ø	1100
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 4/10/17	
Phone:	
Witness: <i>[Signature]</i>	