## FLARE INSPECTION

BC Operating LEASE OR FACILITY NAME Angel B	
WELL #	
U.L. ASEC 11 T 175 R 36E	
FOOTAGE 660 DS 660 EIW	
IS A FLARE STACK PRESENT? YES NO	
IS FLARE ACTIVE? YES NO	
IS GAS TO FLARE METERED? YES	
AREA AROUND FLARE CLEARED? VES NO	
ENVIRONMENTAL CONCERNS	
IS VRU PRESENT? YES NO	
IS VRU ACTIVE? YES NO	
COMMENTS	
INSPECTOR Glacy Colonsia DATE 5-8-17	