

4.25.

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

MAY 08 2017

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron MidContinent USA INC		API Number 3002536451	
Property Name Trinity Burris Abo Unit		Well No. 5	
7. Surface Location			
UL - Lot F	Section 23	Township 12S	Range 38E
Feet from 2310		N/S Line N	Feet From 1650
E/W Line W		County LEA	

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 4-17-17	Inj
-------------	---------	-----------	------------------------	------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	0	0	700
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR N/A	FRESH N/A	SALTY N/A	SULFUR N/A	BLACK N/A
------------------	------------------	------------------	-------------------	------------------

Remarks: INJECTING AT THIS TIME **X** WTR, ___ GAS, ___ CO2

Signature: Justin Wall	OIL CONSERVATION DIVISION
Printed name: Justin Wall	Entered into RBLMS
Title: Field Specialist	Re-test X 7
E-mail Address: LJWK@Chevron.com	
Date: 4-17-17	
Phone: 575-704-6224	
5.3.17	Witness: