Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283	strict II - (575) 748-1283		30-025-25733
D' . ' . III (505) 224 (150	1.5.1 11.5.1 15.1 15.1 15.1 15.1 15.1 1		5. Indicate Type of Lease
1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztee, NM 87410 District IV – (505) 476 3460 B 50 C D Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		or state on as sas Boast Inc.	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR AISE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			CENTRAL VACHUM UNIT
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			CENTRAL VACUUM UNIT  8. Well Number #93
1. Type of Well: Oil Well Gas Well Other INJECTION			
2. Name of Operator CHEVRON USA INC			9. OGRID Number 4323
3. Address of Operator			10. Pool name or Wildcat
1616 W. BENDER BLVD HOBBS, NM 88240			VACUUM; GRAYBURG; SAN ANDRES
4. Well Location  Unit Letter M: 10 feet from the SOUTH line and 1136 feet from the WEST line			
Section 31 Township 17S Range 35E NMPM County LEA  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3682' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBS			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
<del>-</del>	HANGE PLANS	COMMENCE DRIL	
PULL OR ALTER CASING M DOWNHOLE COMMINGLE	ULTIPLE COMPL	CASING/CEMENT	JOB L
CLOSED-LOOP SYSTEM			
OTHER:			AIR WELL/MIT CHART
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
CHEVRON USA INC HAS REPAIRED THE ABOVE WELL AS FOLLOWS:			
AAMAAAA AMBUU BUCTAU L DOD TECT TO ASA BOW ON/SAA BOWNON			
<b>04/18/2017</b> MIRU, INSTALL BOP, TEST TO 250 PSILOW/500 PSI HIGH. <b>04/19/2017</b> RIG UP SCANNERS AND PULL OUT OF HOLE, KEEPING YELLOW BAND, RIH WITH ON /OFF TOOL			
04/20/2017 PULL OUT WITH PACKER. RUN IN WITH RBP AND PACKER TO 4290' AND TRY TO SET AND TEST			
RBP.			
CONTINUED ON NEXT PAGE			
Spud Date:	Rig Release Da	te:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
$\Delta = 0.01$			
SIGNATURE ( DATE 05/03/2017 DATE 05/03/2017			
Type or print name CINDY HERRERA-MURILLO E-mail address: Cherreramurillo@chevron.com PHONE: 575-263-0431			
For State Use Only M   M   A   A   A   A   A   A   A   A			
APPROVED BY: Y ALLY DIOWY TIPLE AD/II DATE 5/10/2017			
Conditions of Approval (if any):		1	

## CASING REPAIR PROCEDURE CONTINUED

04/21/2017 Check pressure. Pull tubing and packer out of the hole. Rig up Phoenix and run Gyro. Rig Down Phoenix. RBP @4290' Casing tested good.

04/24/2017 Pressure on well Zero/ Intermediate Casing and Surface Casing had 20 PSI, both bled off/ RU QES and perform CBL and CIL/ Shut down due to high winds and strong gusts.


04/25/2017 RIH with retrieving tool and POOH with RBP form 4281' to surface/pump down 7" and instant communication/Shut down due to high winds.

04/26/2017 900 PSI on well, Bled down- Kill well/RIH with 4 1/2'" packer and set @ 4281'/ Pumped 350 BBLS down tubing and no communication on 7" casing and 9 5/8"/ Pump a dye down the 7" casing and within  $\frac{1}{2}$  BBL we seen the dye out the 9 5/8"/ Attempted to get injection down 9 5/8' but instant pressure on both 95/8' AND 7" Casing/ Bled off pressure and POOH with test packer/ RIH with 4  $\frac{1}{2}$ " production injection packer and set @ 4257'/ Shut Pipe Rams and shut down.

04/28/2017 RIH with Production tubing while pressure testing to 5000 PSI/ Pre- test to 500 PSI for 30 minutes /Test Good/ Circulate packer fluid/ NDBOP/ NU injection tree / Burst pump out plug @ 1400 PSI/ Prep to Rig down Monday morning after MIT Test.

05/01/2017 Run MIT test for 30 minutes @ 520 PSI (held). Rig down, Turn well over to FMT. Final Report.

\*\*\*Original MIT Chart and a copy is attached\*\*\*



102.1-2 102.1-2 0 Field Vacuum Crayburg son miles 121-12 00 5751-84 35037 75 M 937731 7.100 EELSESEOUS IN