

HOBBS OCD
MAY 10 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.	API Number 30-025-04060
Property Name NMGSAU	Well No. 907

Surface Location

UL - Lot G	Section 25	Township 19S	Range 30E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒	SWD ☐	PRODUCER OIL ☐ GAS ☐	DATE 5-5-17
--	--	--	------------------------------	---	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	730
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: JD Ellison	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Tech	Re-test
E-mail Address: JD.Ellison @ apache corp.com	
Date:	
Phone: 575-411-7734	
Witness: Shay Palmer	