

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp. **API Number** 30-025-05722 ✓
Property Name NMGSAN **Well No.** 1103

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	29	195	37E	660	N	1980	W	Lea

Well Status

YES	TA'D WELL	YES	SHUT-IN	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
	NO		NO							5-5-17

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csing	(E)Tubing
Pressure	0	0	N/A	0	1050
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>JD Ellison</i>	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Tech	Re-test
E-mail Address: JD.Ellison @ apache corp. com	
Date:	
Phone: 575-441-7734	
Witness: <i>Cheryl Robinson</i>	