

HOBBS OCD
MAY 10 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.	API Number 30-025-05725
Property Name NMGSAU	Well No. 1111

Surface Location

UL - Lot K	Section 29	Township 19S	Range 37E	Feet from 1980	N/S Line 5	Feet From 1980	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ (INJ)	SWD	OIL	PRODUCER GAS	DATE 5-5-17
------------------	----	----------------	----	---------------------	-----	-----	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	N/A	0	1050
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks— Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod casing blew down in 30 sec.

Signature: JD Ellison	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Tech	Re-test
E-mail Address: JD.Ellison @ apache corp. com	
Date:	
Phone: 575-441-7734	
Witness: Dave Robinson	