

HOBBS OCD
MAY 10 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.	API Number 30-025-05747
Property Name NMGSAU	Well No. 1005

Surface Location

UL - Lot E	Section 30	Township 19S	Range 37E	Feet from 1980	N/S Line N	Feet From 6600	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	SWD NO	OIL NO	PRODUCER NO	GAS NO	DATE 5-5-17
-------------------------	-----------------------	------------------------	------------------	------------------	-----------------------	------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	N/A	0	730
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod blew down in 15 sec.

Signature: Jim Ellison	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Tech	Re-test
E-mail Address: JD.Ellison @ apache corp.com	
Date:	
Phone: 575-441-7734	
Witness: Ray Robinson	