

**SHACKELFORD OIL COMPANY**

**203 W. Wall STE 200**

**Midland, TX 79701**

**DESIGN:** Closed-Loop system with roll-off steel bin (pits)

**Contacts:** Bob Shackelford – Office: 432-682-9784 Cell: 432-813-7090

Art Marquez – Office: 432-682-9784 Cell: 575-405-1334

**Monitoring:** 12 hour service

**Equipment:**

500 bbl waste fluid tank

500 bbl brine water tank

  
Pump, swivel manifold

Reverse tank

1 CRI Bin with track system

Air pumps on location for immediate remediation process

Layout of Closed Loop System with bin, attached

Cuttings and associated liquids will be hauled to a State regulated third party disposal site, via CRI (Controlled Recovery, Inc.) Disposal Facility Permit # R9166

**OPERATIONS:**

Closed Loop equipment will be inspected daily by each tour and any necessary maintenance performed.

Any leak in system will be repaired and/or contained immediately.

OCD will be notified within 48 hours of the spill.


Remediation process started immediately:

**CLOSURE:**

During drilling operations all liquids, drilling fluids and cuttings will be hauled off via CRI (Controlled Recovery Incorporated) Disposal Facility Permit # R9166

LUSK FEDERAL #8-A

## RIG LAYOUT



1. WELL SERVICE RIG
2. REVERSE UNIT
3. REVERSE PIT
4. WASTE FLUID TANK
5. WASTE FLUID TANK
6. SOLIDS BIN
7. 500 BBL. FRAC TANK
8. MANIFOLD

**EXHIBIT D**

**LUSK FEDERAL #8-A  
V-DOOR EAST  
Rig Up West**

NORTH

