

HOBBS OCD

MAY 25 2017

State of New Mexico

Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

REC'D/MIDLAND

MAY 15 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28923
Property Name Seven Rivers Queen Waterflood, North	Well No. 10

7. Surface Location

UL - Lot F	Section 4	Township 22S	Range 36E	Feet from 2623	N/S Line North	Feet From 1330	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL ☒ YES	☒ NO	SHUT-IN ☒ YES	☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 5-12-2017
--	--	--	--	---	-----	-----	-----------------	-------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csng	(E) Tubing
Pressure	Ø	Ø		Ø	140
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 ____
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ____
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ____
Down to nothing	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Alan Miller - XTO</i>	OIL CONSERVATION DIVISION
Printed name: <i>ALAN MILLER</i>	Entered into RBDMS
Title:	Re-test <i>[Signature]</i>
E-mail Address:	
Date: <i>5-12-2017</i>	Phone: <i>575-441-1641</i>
Witness:	