

FLARE INSPECTION

Manzano
LEASE OR FACILITY NAME Sodbuster 21 FEG

WELL # 4H API# 30-250 - 43704

U.L. N SEC 21 T 9S R 35E

FOOTAGE 200 N / S 1150 E / W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS Combustor lagging on ground to be hooked up.

INSPECTOR Greg Robinson DATE 6-5-17