

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUN 02 2017

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06754	
Property Name NEDU (Northeast drinkeed unit)		Well No. 904	

1. Surface Location

UL - Lot K	Section 22	Township 21S	Range 37E	Feet from 2065	N/S Line S	Feet From 1700	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------


Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ IN ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 6/1/17
--	--	---	---	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	Ø	N/A	N/A	Ø	1175
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Wellhead if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title: Pumper		Re-test 	
E-mail Address: Tracy.Cole@apachecorp.com			
Date:	Phone: 575-441-5196		
Witness:			