

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

HOBBS OCD
 JUN 02 2017
 RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.	API Number 30-025-06771
Property Name NEDU (Northeast drained unit)	Well No. 811

1. Surface Location

UL - Lot E	Section 23	Township 28	Range 37	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County Lea
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER ☐ GAS	DATE 5/31/17
--	--	---	-----	-----	--	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	$\emptyset$	$\emptyset$	N/A	$\emptyset$	1160
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Inferred for Wellhead & applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole	OIL CONSERVATION DIVISION
Printed name: Tracy Cole	Entered into RDBMS
Title: Pumper	Re-test
E-mail Address: Tracy.Cole@apachecorp.com	
Date: 5/31/17	
Phone: 575-441-5196	
Witness:	