

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD

JUN 02 2017

RECEIVED

Operator Name Apache Oil Corp.	Property Name NEDU (Northeast drilled unit)	Well No. 611
--	---	------------------------

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
G	15	21	37E	1980	N	1978	E	Lea

Well Status

TA'D WELL ☒ YES	NO	SHUT-IN ☒ YES	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 6/1/17
--	----	--	----	-----	----------	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	$\emptyset$	$\emptyset$	N/A	$\emptyset$	125#-0*
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	CO2 ☐
Steady Flow	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	WTR ☐
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Type of Fluid
Gas or Oil	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	Injected for
Water	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	Watershed & applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Tubing had 125# blew down in less than 1 min. to 0# gas mist of water

Signature: Tracy Cole	OIL CONSERVATION DIVISION
Printed name: Tracy Cole	Entered into RBDMS
Title: Pumper	Re-test
E-mail Address: Tracy.Cole@apachecorp.com	
Date: 6/1/17	
Phone: 575-441-5196	
Witness:	