

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-005-60248
5. Indicate Type of Lease STATE FEE X ✓
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit ✓
8. Well Number 074 ✓
9. OGRID Number 269864
10. Pool name or Wildcat Twin Lakes; San Andres (Assoc)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3951

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other Injection

2. Name of Operator
 State of New Mexico formerly Canyon E&P Company ✓

3. Address of Operator
 811 South 1st Street, Artesia, NM 88210

4. Well Location
 Unit Letter K: 1980 feet from the South line and 1980 feet from the West line
 Section 1 Township 9S Range 28E NMPM Chaves County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF IF PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> OTHER: _____	INT TO PA P&A NR <u>pm X</u> P&A R _____	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A XX CASING/CEMENT JOB <input type="checkbox"/> OTHER: _____
---	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Maureen White TITLE P.E.S. DATE 06/15/2017

Conditions of Approval (if any):

Plugging Report TLSAU #74

6/9/2017 Move in and rig up. Ran 2 ¼" gauge ring down both strings of 2 7/8" tubing. Tagged up in string "A" (West) at 1537'. Tagged up in string "B" (East) at 2486'.

6/12/2017 RIH with wireline and perforate string "A" at 1537'. Wireline was stuck after perforating. Worked to get loose and pulled out of the rope socket. Left tools in the hole. Established circulation down string "A" and up 8 5/8" casing. Pumped 70 sx cement down string "A" and out perforations into 8 5/8" casing. Estimated TOC inside 8 5/8" casing is 1379'. Left string "A" full of cement. WOC & SION.

6/13/2017 RIH and perforated string "B" at 1000'. Established circulation up 8 5/8" casing and squeezed with 50 sx with CaCl. WOC and tagged at 778'. Perforated string "B" at 200' and circulated cement to surface with 50 sx cement. Cut off wellhead. Filled up everything with 10 sx cement and installed marker. Cut off anchor, cleaned pit and cleared location.