

HOBBS OCD
JUN 13 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-29757
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 219

7. Surface Location

UL - Lot D	Section 3	Township 19-S	Range 38-E	Feet from 657	N/S Line NORTH	Feet From 787	E/W Line WEST	County LEA
---------------	--------------	------------------	---------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Yes	PRODUCING	DATE 5-17-17	Injector
-------------	----------------	-----------	-----------------	----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	10	0
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Steady Flow	Y / ☒ N	Y / N	Y / N	☒ Y / ☒ N	
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	☒ Y / N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Shut in for neighboring injector leak.
~~It~~ came out of the production csg with steady flow.
Packer fluid

575-390-6360

Robert Box 5-17-17

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy.johnson@oxy.com	
Date: JUN 12 2017	
Phone: 806-592-6280	
Witness:	