

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28926
Property Name Seven Rivers Queen Waterflood, North	Well No. 13

7. Surface Location

UL - Lot K	Section 4	Township 22S	Range 36E	Feet from 1325	N/S Line South	Feet From 1330	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE 5-12-2017
---	-------------------	---	-----	-----------------	-----	-------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	Ø			Ø	120
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR —
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Alan Miller - XTO</i>	OIL CONSERVATION DIVISION
Printed name: ALAN MILLER	Entered into RBDMS
Title:	Re-test
E-mail Address:	<i>[Signature]</i>
Date: 5-12-2017	
Phone: 575-441-1641	
Witness:	