Submit I Copy To Appropriate District Office	State of New Me			Form C-103
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu		WELL API NO.	Revised August 1, 2011
District II - (575) 748-1283 HOBE	SS OF DONSERVATION	DIVISION	30-025-32003	
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178	1220 South St. Fran	ncis Dr.	5. Indicate Type	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87 3UN <u>District IV</u> – (505) 476-3460	26 2017 Santa Fe, NM 8	7505	6. State Oil & Ga	FEE
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTIC	EVED LES AND REPORTS ON WELLS	3	7. Lease Name of	r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS.	ALS TO DRILL OR TO DEEPEN OR PL	UG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLIC: PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) FO	UK SUCH	Redhawk 32 State	
	Gas Well 🔲 XX Other SWD		8. Well Number	# 2
2. Name of Operator Basic	Energy Services LP		9. OGRID Numb 246368	er
3. Address of Operator	shergy services Li		10. Pool name or	Wildcat
801 Cherry	Street Suite 2100 Fort Worth TX	76102	Delaware	
4. Well Location				
	feet from the <u>South</u> line and			
Section 32	Township 19 S Range 34	And the second	County 1	Lea
	11. Elevation (Show whether DR	, <i>KKB</i> , <i>K</i> 1, <i>GR</i> , <i>etc.</i>)		
12. Check A	ppropriate Box to Indicate N	lature of Notice,	Report or Other	Data
NOTICE OF INT		CUD		
		REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DRI	Accessed and a second	P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	ГЈОВ	
OTHER:		OTHER:		
13. Describe proposed or comple	eted operations. (Clearly state all]	pertinent details, and	d give pertinent date	es, including estimated date
	k). SEE RULE 19.15.7.14 NMAG	C. For Multiple Con	npletions: Attach v	vellbore diagram of
proposed completion or reco	inpletion.			
Plance see and eccent the att	ached two names annot of anno-dia	l annala dana an tha D	adhards 22 State #	2
MIT to be done on 6/22/17/	ached two page report of remedial	I work done on the F	Cednawk 32 State #	2.
Spud Date:	Rig Release Da	ate:		
		L		
I hereby certify that the information a	bove is true and complete to the b	est of my knowledge	e and belief.	
D. OH				
SIGNATURE David H. Alvarad	do TITLE	SENM District Flui	ds Mgr.	DATE 6/21/17
The second		1.01.1		
Type or print name David H. Alvarad For State Use Only	<u>e</u> E-mail address: <u>david.alvar</u>	rado(a)basicenergyse	rvices.com PHON	E: <u>575. 746. 2072</u>
	AKAN	ADIT		1.121/2014
APPROVED BY:	S DIOWTATLE	NUII	DA	TE COCCO AUT
Conditions of Approval (if any):)	1		/ /
	DON ME - Allan	~ /		
	RBDMS - CHAR	1-1		

	BAMS	~	CHART-	~	
--	------	---	--------	---	--

Redhawk 32 State # 2

API 30-025-32003

C-103 Subsequence Detail of work

5/31/17	Tested	Anchors v	with H	lobbs A	nchors	(testing g	(ood.)
---------	--------	-----------	--------	---------	--------	------------	--------

- 6/1/17 MI RU Renegade Slick Line TIH with gauge ring stuck at 60' POH backflow 150 bbls. To frac tank. Ru PSI Trk. Pump 75 bbl. F/W. TIH w/ gauge ring to 2270' tight spot run to 5526' profile nipple. Plug will not set. POH with plug. Attempt second time set held. SDFN
- 6/2/17 MI PU all needed equipment Ru service unit over matting board, NU BOP open annulus no PSI, ready BOP, racks, catwalk. ND well head NU BOP. MI RU snubbing unit. SDFN
- 6/3/17 Open Csg. No Psi, open tubing 1500 psi flow back to frac tank. Flow very light plug not set correctly call for Slick line to retrieve plug. NU Master valve back wait on Renegade, POH with Plug. Plug packing shows bad. Plug is 2.812 X Odis type. SDFN
- 6/4/17 Trip in the hole with plug (2.812 X plug) Will not set. TOH with Plug Call in for HCL 15% NEFE 12 bbl. SDFN
- 6/5/17 NU Kill truck and Kel-Tech. acid. Pump 660 gal NEFE 15% holding across Pkr. Displace with 38.5 bbl F/W. Shut in well. Unload and tally 240 jts 2 7/8 L80 working string. SDFN
- 6/6/17 TIH with plug will not set had a profile brought to location so Renegade and test their plug in their shop. SDFN
- 6/7/17 RU Slick Line attempt to set plug in profile hanging up not setting select dogs POH redress packer change to Baker type packing on plug. SDFN
- 6/8/17 Ru Kill truck and placed 1000 psi in well bore TIH with plug set (good) released psi off Annulus and tubing Ru BES Scan loggers released O/O tool TOH with tubing found 61 jnts bad ranging 31%-100% bad. Call in for new 3.5 9.3# J-55 totaling 1964'. TIH with working string 2 7/8 L80 to 5382' with O/O tool SDFN.
- 6/9/17 Open BOP TIH with 176' 2 7/8 to top of pkr. MI RU Snubbing Unit pump fluid in tubing to fill displacement. O/O tool will not set on profile wash over profile w/310 bbl set back on profile set and locked. Placed 1000 PSI on casing to unset packer. Found Companion Flange above well head to be leaking. Rig down Snubbing unit call for 10 ¾" companion flange, Call in for Larkin 92 well head and 10 ¾" flange SDFN.
- 6/10/17 ND old well head and replaced with new companion flange. RU Snubbing unit. SDFN
- 6/11/17 SDFN
- 6/12/17 Released BOP TOH with Pkr. Pkr. Shows in good shape found scale around body. Profile nipple sustained scratches sent in Pkr. For redress and new Profile 2.812X profile. SDFN

- 6/13/17 Released BOP TIH with 6 ¼" bit w/ BHA and tubing to Tag of fill at 5703' cleaned to 5775' closed well in. SDFN
- 6/14/17 Ready to continue cleanout at 5775' cleaned well bore to 6218' close well in. SDFN
- 6/15/17 Continue to lean out to 7310' ND swivel placed T/W valve on tubing. NU Kill truck and acid pumped 30 bbl f/w , 80 bbl 15% NEFE, 43 bbl F/W for displacement . TOH with 2 7/8 tubing laying down on rack. SDFN
- 6/16/17 Continuance TOH with 2 7/8 L80 working string and laying down Release working string, switched BOP rams to 3.5". BHA 3.5 X 7" Nickel coated Arrow Set w/ S/S 2.812X profile nipple and on/off tool placed pop off plug w/ four set screws at bottom on Pkr. Pop off set to release at 3400 PSIG. Ready snubbing unit to run Pkr. and production string back in. Found that fingers on snubbing bladder element hitting collars. Call for welder to dress bladder. TIH with 81 jnts. SDFN.
- 6/17/17 Continue TIH with 3.5 J55 9.2# EUE tubing Set Pkr. @ 5542.01 ft. Attempt was made to get off the on/off tool will torque to the right but felt soft to the left to release tool. Lost weight after few attempts. POH with 2600 ft. of tbg. Call in for 3.5 collar overshot with 7" shoe secure well SDFN.
- 6/18/17 SDFN Father's Day.
- 6/19/17 Problems with Snubbing Units Engine Turbo went out Call for new Turbo and Mechanic to fix. SDFN
- 6/20/17 TIH with Over shot and 2 7/8 one joint w/ 2.25R profile with plug and working string to 2600' set on collar and caught fish. Unset On/Off tool from Pkr. TOH with fish laying down 2 7/8 L80 replaced Collar and joint TIH with 3.5 9.2# J-55 to top of Pkr.. RD snubbing unit and released. ND spools to the BOP. Ru pump trk. Circulated 340 bbls 3% KCL. Set back on packer ND BOP, NU well head, tested annulus to 650 PSIG for 30 min Held good. RU PSI hose on master valve and blew pop off plug at 3200 PSIG. Shut in master and released Service unit and PSI trk. SDFN
- 6/21/17 Call made to District I Hobbs for date and time for MIT. MIT will take place on 6/22/17 C-103 will be filed after MIT test.
- 6/22/17 MIT was done witnessed by Kerry Fortner held 580 PSIG for 32 min. also Bradenhead test report was done also good. Please accept the following:
 - Chart of MIT performed.
 - Chart Meter Calibration Certificate # A483
 - Bradenhead Test Results for the Redhawk 32 State # 2

Dance Harris E-26-17



TD @ 13,612'



*

AMI

Artesia Office

416 East Main Street P.O. Box 1836 Artesia, New Mexico 88211 Office: (575)746-3481 Toll Free: 1-888-421-9453

Calibration Certificate

Company Name:	Basic Energy Services	
Recorder Type:	Barton 8"	
Recorder Serial:#	A483	

 Recorder Pressure Range:
 0-1000#
 Accuracy +/-: 0.2%
 PSIG

 Temperature Range:
 Deg F.

Increasing Pressu	Ire	Decreasing Pressure					
Applied	Indicated	Error%	Applied	Indicated	Error%		
Pressure	Pressure		Pressure	Pressure			
0.0#	0.0#	0	800#	800#	C		
100#	100#	0	600#	600#	C		
300#	300#	0	400#	400#	C		
500#	500#	0	200#	200#	C		
700#	700#	0	0.0#	0.0#	0		
1000#	1000#	0					

Temperature Te		
Applied	Error%	
Temperature	Temperature	

Certified Calibration Instrument Used

Gauge: Crystal

Deadweight:

Remarks:

Calibration Date: 1/26/2017

Technician:

Butter Craig Sutherland

District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

				BRAD	ENHEA	D TEST	r REI	PORT	8			
								Name			API Numb	er
						Basic Ene	rgy Se	rvices	30-	-025-320		
			Pi	roperty N	ame						W	ell No.
Red Ha	wk 32 S	tate									002	
					7. Surface	Location	1					
UL - Lot	Section	Township	Range		Fe	et from	N/S	Line	Feet Fr	rom	E/W Line	County
J	32	19-S	34-E		19	080	S		198	0	E	LEA
					Well	Status						
TA'I	Well		SHUT-IN		INJ	ECTOR		ł	PRODUC	ER	1	DATE
YES	NO			NO	INJ	SH		OIL	,	GAS	6	-22-17
	((9	OBSERV	ED DAT	<u>[A]</u>					
		(A)S	urf-Interm	(B)Inter	rm(1)		(C)Inter	m(2)		(D)Prod C	sng	(E)Tubing
Pressure			(2)		-	-					0	0
Flow Charac	teristics											NOTINO
Puff			VTO		Y/N			Y/N		Ø	/ N	C02
Steady F	low		Y/O		Y/N			Y/N		Y	0	WTR
Surge	5		Y/ S		Y/N			Y/N		Y	10	GAS
Down to no	othing		07 N		Y/N			Y/N		-	7 N	If applicable type
Gas or	Oil		Y/ Ø		Y/N			Y/N		Y	70	fluid injected for

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down	or continuous build up if applies.
Signature: Deal Car	OIL CONSERVATION DIVISION
Printed name: BLAINE PAUL	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 6-22-17 Phone: 575-513-1066	
Witness: KERRY FORTNER-OCD 575-399-3221	