## State of New Mexico

## Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office												
BRADENHEAD TEST REPORT												
- 🗴	B. C.	16/20 14		3. API Number 30-025-07598								
Property Name SOUTH HOBBS (G/SA) UNIT									Well No.			
7. Surface Location												
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County			
Α	4	19-S	38-E		660	NORTH	660	EAST	LEA -			
				V	Vell Status							
Well Status			SHUT-IN	SHUT-IN			DATE					
_			NO		Oil	6	-12-17		_			
	OPE	N BRADEN	HEAD AND INT	ERMEDIATE T	O ATMOSPHER	E INDIVIDUALLY	Y FOR 15 MINUT	TES EACH				
If bradenhead	flowed was	ter, check all	of the description		ERVED DATA	A						

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0	NIA	NIA	366	4/8
Flow Characteristics					
Puff	◎/ N	Y/N	Y / N	Y/N	
Steady Flow	Y / 🕥	Y / N	Y / N	Y/N	
Surges	Y/N	Y/N	Y / N	Y/N	
Down to nothing	Ø/ N	Y/N	Y / N	Y / N	_
Gas or Oil	Ŷ N	Y / N	Y / N	Y / N	$\dashv$
Water	Y/N	Y/N	Y/N	Y/N	_

If bradenhead flowed water, check all of the descriptions that apply: CLEAR FRESH **SULFUR** BLACK Remarks: INJECTING AT THIS TIME\_\_\_ WTR, GAS, Surface Puch down to 0 DC; And Jul Saved TUCKY 5754338992

Signature: Mendy	Johnn	OIL CONSERVATION DIVISION		
Printed name: MENDY JOHNSON		Entered into RBDMS		
Title: ADMINISTRATIVE ASSOCIAT	E	Re-test		
E-mail Address: mendy_johnson@oxy	com	gnt		
Date: JUN 2 1 2017	Phone: 806-592-6280			
	Witness:			