

JUL 7 2017

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <u>Mowbourn Oil Company</u>	API Number <u>30-025-31115</u>
Property Name <u>Querecho Plains BS sand Wt</u>	Well No. <u>16-1</u>

7. Surface Location

UL - Lot <u>L</u>	Section <u>24</u>	Township <u>18-S</u>	Range <u>32-E</u>	Feet from <u>2310</u>	N/S Line <u>S</u>	Feet From <u>330</u>	E/W Line <u>W</u>	County <u>Lea</u>
----------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒	SHUT-IN <u>YES</u> ☒	INJECTOR <u>INJ</u> ☒	PRODUCER <u>PROD</u> ☒	DATE <u>4-25-2017</u>
---	--	---	--	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<u>0</u>	<u>—</u>	<u>—</u>	<u>0</u>	<u>0</u>
Flow Characteristics					
Puff	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	CO2 <u>—</u>
Steady Flow	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	WTR <u>—</u>
Surges	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	GAS <u>—</u>
Down to nothing	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	
Water	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	<u>Y/N</u>	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

MIT Failure - Communication to surface

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness:	