dI
N. French Dr., Hobbs, NM 88240
one: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD
JUL 7 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Newbourne Oil Company	30-025-40162
Property Name	**Well No.**
Red Hills West SWD	1

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
P	16	26S	32E		700	S	690	E	Lea

Well Status

TA'D Well		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	~~NO~~	YES	~~NO~~	INJ	~~SWD~~	OIL	GAS	5/18/2017

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	—	—	0	0
Flow Characteristics					
Puff	~~Y~~ / N	Y / N	Y / N	~~Y~~ / N	CO2 _____
Steady Flow	Y / ~~N~~	Y / N	Y / N	Y / ~~N~~	WTR _____
Surges	Y / ~~N~~	Y / N	Y / N	Y / ~~N~~	GAS _____
Down to nothing	~~Y~~ / N	Y / N	Y / N	~~Y~~ / N	If applicable type
Gas or Oil	Y / ~~N~~	Y / N	Y / N	Y / ~~N~~	fluid injected for
Water	Y / ~~N~~	Y / N	Y / N	Y / ~~N~~	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump not working

Signature:		**OIL CONSERVATION DIVISION**
Printed name:		**Entered into RBDMS**
Title:		**Re-test**
E-mail Address:		
Date:	**Phone:**	
	Witness:	