

HOBBS CD
RECEIVED
JUL 10 2017

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache		* API Number 30-025-37513
Property Name Edith Butler B		Well No. 4

2. Surface Location

UL - Lot I	Section 13	Township 22	Range 37	Feet from 1980	N/S Line S	Feet From 850	E/W Line E	County Lea
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJ ☐	INJECTOR SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 6/14/17
---	---	------------------------------	--	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	30	30
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	N / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Ryle Messinger		OIL CONSERVATION DIVISION	
Printed name: Ryle Messinger		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: ryle.messinger@apachecorp.com		mt	
Date: 6/14/17	Phone: 575-441-1022		
Witness: Don			