

HOBBS OCD

JUL 10 2017

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <u>Apache Corporation</u>		API Number <u>30-025-09177</u>	
Property Name <u>South Eunice Seven Rivers Queen Unit</u>		Well No. <u>414</u>	

2. Surface Location

UL - Lot <u>0</u>	Section <u>36</u>	Township <u>22S</u>	Range <u>36E</u>	Feet from <u>330</u>	N/S Line <u>S</u>	Feet From <u>2310</u>	E/W Line <u>E</u>	County <u>Lea</u>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE <u>6-7-2017</u>
--	--	--	---	-------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	<u>0</u>			<u>0</u>	<u>105</u>
Flow Characteristics				<u>0</u>	
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 —
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR <u>X</u>
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS —
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <u>Kyle Messimer</u>		OIL CONSERVATION DIVISION	
Printed name: <u>Kyle Messimer</u>		Entered into RBDMS	
Title: <u>Pumper 2</u>		Re-test	
E-mail Address: <u>kyle.messimer@apachecorp.com</u>		<u>MB</u>	
Date: <u>6-7-2017</u>	Phone: <u>575-441-1022</u>		
Witness:			