

JUL 1 9 2017

## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

# RECEIVED

# **BRADENHEAD TEST REPORT**

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating								- 30-025-30374			×	
	1	Property Name SKELLY PENROSE B UNIT								We 68	ell No.	2
					7. Su	rface Location	n					
	UL - Lot J	Section 54	Township 23S	Range 37E		Feet from 1340	N/S Line SOUTH	Feet From 1350		E/W Line EAST	County LEA	

### Well Status

Ta' D Well	SHUT-IN	INJECTOR	PRODUCING	DATE	
No	No		Oil	07/06/2017	-

#### OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

# OBSERVED DATA

## If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	<u> </u>			42	42
Flow Characteristics					
Puff	N	Y / N	Y / N	Y / N	_
Steady Flow	N	Y/N	Y/N	Y - N	
Surges	N	Y/N	Y / N	Y - N	
Down to nothing	Y	Y / N	Y / N	Y / N	
Gas or Oil	N	Y/N	Y / N	Y / N	_
Water	N	Y / N	Y / N	Y/N	

## If bradenhead flowed water, check all of the descriptions that apply:

CLEAR FRESH	SALTY	SULFUR	BLACK	
-------------	-------	--------	-------	--

Remarks:		

Signature:	Durke	OIL CONSERVATION DIVISION		
Printed name: C. DALE KELTON		Entered into RBDMS		
Title: PRESIDENT		Re-test -	25	
E-mail Address: providenceenergy@su	Iddenlink.net		MP	
Date: 07/14/2017	Phone: 432-661-1364			
	Witness:		V	