HOBBS COD

State of New Mexico Energy, Minerals and Natural Resources Department

JUL 1 9 2017

Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

	DD OV HD	CLICE ELIED	Operato		W. t. O					API Numb	er	
PROVIDENCE ENERGY SERVICES, INC., and Kellon Operating								30-025-32112 Well No.				1
Property Name SKELLY PENROSE B UNIT										71		_
					7. Surface Locat	ion						
UL - Lot Section Township K 5 23S		Range 37E		Feet from 1420		N/S Line Feet SOUTH			E/W Line WEST	County LEA		
					Well Status	5						
Ta' D Well No			shut-in No		INJECTOR		PRODUCING Oil			07/06/2017		
	OPE		HEAD AND IN		IATE TO ATMOSPHI OBSERVED DA		VIDUALI	LY FOR 15 M	INUTES	EACH		
		(A)Su	(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure		,	N/A	+					24		24	
Flow Chara	cteristics											
Puff			Y / N	+	Y / N		Y / N		Y / N		-	
Steady Flow			Y/N		Y / N	Y / N			Y - N			
Surges			Y / N	Y / N			Y / N		Y - N			
Down to nothing			Y / N	Y / N			Y / N		Y / N			
Gas or	Oil		Y/N	Y/N		Y / N			Y / N			
Water			Y/N		Y/N	Y / N			Y / N			
If bradenhead flowed water, CLEAR			FRESH		ons that apply: SALTY		SULFUR		BLACK			
Remarks: Possibly Cem	ented to Sw	rface.										
Sionature			Duk	~							N DIVISION	
Printed name: C. DALE KELTON								Entered into RBDMS				
Title: PRES			dd P-1					Re-test			MI	
		enceenergy@	suddenlink.net								1	
Date: 07/14/2017 Phone: 432-661-1364											V	

Witness: