

7.17.17

HOBBS OCD
AUG 02 2017

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A.	API Number 30-025-12309
Property Name WDD4 West Dollarhide Drinkard Unit	Well No. 60

7. Surface Location

UL - Lot F	Section 32	Township 24S	Range 38E	Feet from 2130	N/S Line S	Feet From 510	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 7/10/17
---	---	--	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	-	-	0	1400
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: LaQuayne Wright Artificial Lift Corrosion Rep. lwq@chevron.com (432)-270-8389	LA-W	OIL CONSERVATION DIVISION
Date: 7/10/17	Phone:	Entered into RBDMS
Witness: Sower		Re-test

INSTRUCTIONS ON BACK OF THIS FORM