

7.17.17

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD
AUG 02 2017

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Chevron U.S.A.</i>	API Number <i>30-025-12314</i>
Property Name <i>WDDU West Dollarhide Drinkard Unit.</i>	Well No. <i>69</i>

7. Surface Location

UL - Lot <i>2</i>	Section <i>32</i>	Township <i>24S</i>	Range <i>38E</i>	Feet from <i>660</i>	N/S Line <i>S</i>	Feet From <i>1830</i>	E/W Line <i>W</i>	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL ☒ YES	☒ NO	SHUT-IN ☒ YES	☐ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER ☐ GAS	DATE <i>7/10/17</i>
--	--	--	-----------------------------	---	-----	-----	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	<i>φ</i>	<i>—</i>	<i>—</i>	<i>φ</i>	<i>φ</i>
Flow Characteristics					
Puff	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	CO2 <i>—</i>
Steady Flow	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	WTR <i>—</i>
Surges	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	GAS <i>—</i>
Down to nothing	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	Type of Fluid
Gas or Oil	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	Injected for
Water	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	<i>Y / N</i>	Waterflood if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:

LaQuayne Wright
Artificial Lift Corrosion Rep.
weq@chevron.com
(432)-270-8389

7/10/17

Witness:

[Signature]

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test

[Signature]

INSTRUCTIONS ON BACK OF THIS FORM