

7-17-17

HOBBS OCD
AUG 02 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>U.S.A.</i>	API Number <i>30-025-30830</i>
Property Name <i>WDDU West Dollarhide Drinkard unit</i>	Well No. <i>108</i>

7. Surface Location

UL - Lot <i>M</i>	Section <i>33</i>	Township <i>24S</i>	Range <i>38E</i>	Feet from <i>1201</i>	N/S Line <i>S</i>	Feet From <i>156</i>	E/W Line <i>W</i>	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR INJ ☒ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE <i>7/10/17</i>
---	---	--	--	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>Ø</i>	<i>Ø</i>	<i>—</i>	<i>Ø</i>	<i>1150</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:

LaQuayne Wright
Artificial Lift Corrosion Rep.
lweq@chevron.com
(432)-270-8389

[Signature]

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test *[Signature]*

7/10/17

Witness: *[Signature]*

INSTRUCTIONS ON BACK OF THIS FORM