

7.17.17

HOBBS OGD
AUG 02 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A.		API Number 30-025-31499
Property Name WDDU West Dollarchide Drinkard unit		Well No. 114

2. Surface Location

UL - Lot C	Section 5	Township 25S	Range 38E	Feet from 108	N/S Line N	Feet From 2325	E/W Line W	County Lea
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL NO	SHUT-IN NO	INJECTOR INJ	SWD	OIL PRODUCER GAS	DATE 7/10/17
------------------------	----------------------	------------------------	-----	----------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	φ	—	—	φ	650
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: LaQuayne Wright Artificial Lift Corrosion Rep. lweq@chevron.com (432)-270-8389 7/10/17		OIL CONSERVATION DIVISION Entered into RBDMS Re-test 7/10/17	
Witness: Bower			

INSTRUCTIONS ON BACK OF THIS FORM