

7.17.17

HOBBS OCD
AUG 02 2017

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Chevron U.S.A.</i>		API Number <i>30-025-31995</i>
Property Name <i>WDDU West Dollahide Drinkard Unit</i>		Well No. <i>181</i>

7. Surface Location

UL - Lot <i>H</i>	Section <i>32</i>	Township <i>24S</i>	Range <i>38E</i>	Feet from <i>2150</i>	N/S Line <i>N</i>	Feet From <i>850</i>	E/W Line <i>E</i>	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR SWD ☒ OIL ☒	PRODUCER GAS ☒	DATE <i>7/10/17</i>
---	---	---	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>0</i>	<i>—</i>	<i>—</i>	<i>0</i>	<i>1400</i>
Flow Characteristics					
Puff	Y / N <i>0</i>	Y / N	Y / N	Y / N <i>0</i>	CO2 ☐
Steady Flow	Y / N <i>0</i>	Y / N	Y / N	Y / N <i>0</i>	WTR ☐
Surges	Y / N <i>0</i>	Y / N	Y / N	Y / N <i>0</i>	GAS ☐
Down to nothing	Y / N <i>0</i>	Y / N	Y / N	Y / N <i>0</i>	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N <i>0</i>	Y / N	Y / N	Y / N <i>0</i>	
Water	Y / N <i>0</i>	Y / N	Y / N	Y / N <i>0</i>	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: LaQuayne Wright Artificial Lift Corrosion Rep. lwq@chevron.com (432)-270-8389 <i>7/10/17</i>	<i>[Signature]</i> Witness: <i>[Signature]</i>	OIL CONSERVATION DIVISION Entered into RBDMS Re-test <i>[Signature]</i>
---	---	---

INSTRUCTIONS ON BACK OF THIS FORM