

HOBBS OCD
AUG 08 2017
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025- 42647 ✓
Property Name SOUTH HOBBS (GISA) UNIT	Well No. 256 ✓

7. Surface Location

UL - Lot I	Section 4	Township 19-S	Range 38-E	Feet from 2188	N/S Line S	Feet From 657	E/W Line E	County LEA
---------------	--------------	------------------	---------------	-------------------	---------------	------------------	---------------	---------------

Well Status

Well Status	SHUT-IN No	PRODUCING	DATE 7-13-17	WAG - Inj
-------------	---------------	-----------	-----------------	-----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	600	N/A	N/A	13	1322
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	☒ Y / N	
Steady Flow	☒ Y / N	Y / N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ☒ GAS, ___ CO2

Surface casing bled to Ops: in 20 sec.

(575)390-6360 Robert Ross

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <u>mendy_johnson@oxy.com</u>	
Date: <u>AUG - 4 2017</u>	Phone: 806-592-6280
Witness:	