

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MIDLAND OPERATING		API Number 30-025-11180
Property Name BLACK		Well No.

7. Surface Location

UL - Lot J	Section 21	Township 24	Range 37	Feet from 1980	N/S Line S	Feet From 1980	E/W Line E	County LEA
---------------	---------------	----------------	-------------	-------------------	---------------	-------------------	---------------	---------------

2 Well Status

TA'D Well YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	DATE 8/24/17
------------------	---------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Victor Sirgo	OIL CONSERVATION DIVISION
Printed name: Victor Sirgo	Entered into RBDMS
Title: Owner	Re-test
E-mail Address: VJSirgo@sbcglobal.net	
Date: 8/24/17	
Phone: [Signature]	
Witness:	