

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
SEP 27 2017
RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07556
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 411

7. Surface Location

UL - Lot A	Section 33	Township 18-S	Range 38-E	Feet from 660	N/S Line NORTH	Feet From 660	E/W Line EAST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status T/A	SHUT-IN T/A	PRODUCING NO	DATE 8-29-17
--------------------	----------------	-----------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	2	2	N/A	2	2
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

T/A - 0.00

Bryan Loftin
575-441-9739

surface A/B had push of gas. Prod csg had Puff of gas w/ prod. water.

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy.johnson@oxy.com	
Date: SEP 21 2017	
Phone: 806-592-6280	
Witness:	