

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD		API Number 30-025-34906
Property Name NORTH HOBBS (G/SA) UNIT		Well No. 511

7. Surface Location

U/L - Lot D	Section 33	Township 18-S	Range 38-E	Feet from 1310	N/S Line NORTH	Feet From 598	E/W Line WEST	County LEA
----------------	---------------	------------------	---------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN NO	PRODUCING Oil	DATE 7-29-17
-------------	---------------	------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	U/A	N/A	154 PSI	548 PSI
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Bryan Leflin
575-441-9739

surface had a puff of gas.

Signature: <i>Mendy Johnson</i>		OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON		Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE		Re-test
E-mail Address: mendy_johnson@oxy.com		
Date: SEP 21 2017	Phone: 806-592-6280	
Witness:		