## HOBBS OCD

OCT 02 2017

Submit One Copy To Appropriate District Office	RECEIVED New Mexico			Form C-103		
District I	Energy, Minerals and Natural Resources			Revised November 3, 2011 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONCEDIVATION DIVIGION			30-025-30967		
811 S. First St., Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Type		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			STATE  6. State Oil & G		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				o. State on & o.	as Lease 140.	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				VACUUM GLORIETA WEST UNIT		
PROPOSALS.)  1. Type of Well:  Gas Well  Other: Injection				8. Well Number #49		
Name of Operator     CHEVRON U S A INC				9. OGRID Number 4323		
3. Address of Operator				10. Pool name or Wildcat		
6301 Deauville Blvd Midland, Texas 79706				VACUUM GLORIETA		
4. Well Location						
Unit Letter M : 990 fi	eet from the SOUTH			feet from the WES		
Section 30	Township 17-S  11. Elevation (Show wh			NMPM	County LE	Α
	3985					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF IN		_	100000000000000000000000000000000000000	SEQUENT_RE		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR						
TEMPORARILY ABANDON				P AND A		
OTHER:				1306		
	l' it oop 1	_	Location is re			PA PM
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.						
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the following:						
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT						
LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.						
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.						
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.						
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well						
location.						
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)						
All other environmental concerns have been addressed as per OCD rules.						
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.						
If this is a one-well lease or last remaining well on lease; all electrical service poles and lines have been removed from lease and well location,						
except for utility's distribution infrastruct	ure.					
When all work has been completed, return this form to the appropriate District office to schedule an inspection.						
SIGNATURE: MANNE	The second	TITLE: _F	IELD SITE MANAGER	DATE: 9/29/17		
TYPE OR PRINT NAME BRYCE W	AGONER E-MAI	L: EWIR@	chevron.com	PHONE: 928-	241-1862	_
For State Use Only						
APPROVED ( 1		2-0			/. /	
BY: Warthhotz	TITLE .:	E.S.		DATE 1	0/02/2	017
Conditions of Approval (if any):						