

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD
OCT 12 2017
RECEIVED

Operator Name EOG Resources		API Number 30-025-30622
Property Name EAST Corbin Delaware		Well No. #1

Surface Location									
UL - Lot M	Section 16	Township 18S	Range 33E		Feet from 548	N/S Line S	Feet From 760	E/W Line W	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 10-2-17	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	900
Flow Characteristics					
Pull	Y/N N	Y/N N	Y/N N	Y/N N	CO2 —
Steady Flow	Y/N N	Y/N N	Y/N N	Y/N N	WTR —
Surges	Y/N N	Y/N N	Y/N N	Y/N N	GAS —
Down to nothing	Y/N N	Y/N N	Y/N N	Y/N N	Type of Fluid
Gas or Oil	Y/N N	Y/N N	Y/N N	Y/N N	Injected for
Water	Y/N N	Y/N N	Y/N N	Y/N N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump down

Signature: Candy Aguilar	OIL CONSERVATION DIVISION
Printed name: CANDY AGUILAR	Entered into RBDMS
Title: Sr. Head Lease Operator	Re-test
E-mail Address: candy_aguilar@eogresources.com	
Date: 10-2-17	
Phone:	
Witness: Harry Robinson	
575-399-3220	

INSTRUCTIONS ON BACK OF THIS FORM