

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
OCT 12 2017
RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOG Resources		API Number 30-025-30736	
Property Name East Corbin Delaware		Well No. #6	

1. Surface Location									
UL - Lot C	Section 21	Township 18s	Range 33E		Feet from 779	N/S Line N	Feet from 1943	E/W Line W	County LEA

Well Status								DATE
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ INJ	SWD	OIL	PRODUCER GAS	10-2-17

OBSERVED DATA

	(A)Surface	(B)Interm(1) <i>sk</i>	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A 0	N/A	0	900
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump down - ~~test~~
Prod. csg. slight water
~~Prod. csg. test hole run another string~~

Signature: <i>Candy Aguilar</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Candy Aguilar</i>		Entered into RBDMS	
Title: <i>Sr. Lease Operator</i>		Re-test	
E-mail Address: <i>candy-aguilar@engresources.com</i>			
Date: <i>10-2-17</i>	Phone:		
Witness: <i>Gary Robinson</i>			

56 575-399-3220

INSTRUCTIONS ON BACK OF THIS FORM