

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
OCT 12 2017
RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOG Resources		API Number 30-025-32915	
Property Name EAST Corbin Delaware		Well No. #9	
Surface Location			
UL - Lot H	Section 21	Township 18s	Range 33E
Feet from 1340		N/S Line N	Feet from 990
E/W Line E		County LEA	
Well Status			
TA'D WELL YES	NO	SHUT-IN YES	NO
INJECTOR INJ		SWD	OIL
PRODUCER GAS		DATE 10-2-17	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	n/a	n/a	0	550
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump down
Prod. csg. slight water
~~Prod. csg. water~~

Signature: Candy Aguilar	OIL CONSERVATION DIVISION
Printed name: Candy Aguilar	Entered into RBDMS
Title: Sr. head lease Operator	Re-test
E-mail Address: candy-aguilar@egoresources.com	
Date: 10-2-17	
Phone:	
Witness: Gary Robinson - 575-399-3220	

INSTRUCTIONS ON BACK OF THIS FORM